



INFORMATION CARD


TCP | TEMPERATURE CHECKPOINT

www.hs-solutions.eu

01

Using the device

MEASUREMENT POSITION




TCP | Temperature checkpoint


www.hs-solutions.eu

RECOMMENDATIONS

01 You need to take off your glasses




02 You need to uncover your forehead




CORRECT POSITION +/- 0,25 °C

Parallel to the screen



NOT RECOMMENDED POSITIONS +/- 0,5 °C

Leaning away from the screen



Leaning towards the screen

